(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
6: Okoboji	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.95
28B: Dickman	Very limited Seepage	1.00	Very limited Seepage	1.00	Very limited Deep to water	1.00
55: Nicollet	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.02	Somewhat limited Deep to water	0.68
			Piping	0.01	Slow refill Cutbanks cave	0.30
62C2: Storden	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
62D2: Storden	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
52E2: Storden	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
73B: Salida	Very limited Seepage	1.00	Very limited Seepage	1.00	Very limited Deep to water	1.00
73E: Salida	Very limited Seepage Slope	1.00	Very limited Seepage	1.00	Very limited Deep to water	1.00
90: Okoboji	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
			Hard to pack	0.75	Cutbanks cave	0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	Embankments, dikes, and levees		.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
95: Harps	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
L07: Webster	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
.35: Coland	Very limited Seepage	1.00	Very limited Depth to saturated zone Piping Seepage	1.00 0.11 0.06	Somewhat limited Cutbanks cave	0.10
l35B: Coland	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
138B: Clarion	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
38C: Clarion	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
38C2: Clarion	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
38D2: Clarion	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
50: Hanska	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Cutbanks cave	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
168B: Hayden	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.10	Very limited Deep to water	1.00
.68C: Hayden	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.10	Very limited Deep to water	1.00
.68D2: Hayden	Somewhat limited Seepage Slope	0.70	Somewhat limited Piping	0.10	Very limited Deep to water	1.00
68E: Hayden	Somewhat limited Seepage Slope	0.70 0.12	Somewhat limited Piping	0.10	Very limited Deep to water	1.00
.75B: Dickinson	Very limited Seepage	1.00	Somewhat limited Seepage	0.97	Very limited Deep to water	1.00
221: Palms	Very limited Seepage	1.00	Very limited Content of organic matter Depth to saturated zone	1.00	Somewhat limited Cutbanks cave	0.10
224: Linder	Very limited Seepage	1.00	Somewhat limited Seepage Depth to saturated zone	1.00	Very limited Cutbanks cave Deep to water	1.00
236B: Lester	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.30	Very limited Deep to water	1.00
236C2: Lester	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.30	Very limited Deep to water	1.00
236D2: Lester	Somewhat limited Seepage Slope	0.70	Somewhat limited Piping	0.30	Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes, and levees		Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
36E2: Lester	- Somewhat limited Seepage Slope	0.70	Somewhat limited Piping	0.30	Very limited Deep to water	1.00
36F: Jester	Somewhat limited Seepage Slope	0.70	Somewhat limited Piping	0.30	Very limited Deep to water	1.00
97: Dundas	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
21: Boots	- Very limited Seepage	1.00	Very limited Content of organic matter Depth to saturated zone	1.00	Somewhat limited Cutbanks cave	0.10
25: Le Sueur	- Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone Piping	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10
19: ∂arfur	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Cutbanks cave	1.00
84: Collinwood	Somewhat limited Seepage	0.01	Somewhat limited Depth to saturated zone Hard to pack	0.09	Somewhat limited Slow refill Deep to water Cutbanks cave	0.99 0.54 0.10
84B: Collinwood	Somewhat limited Seepage	0.01	Somewhat limited Depth to saturated zone Hard to pack	0.09	Somewhat limited Slow refill Deep to water Cutbanks cave	0.99 0.54 0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
386: Cordova	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
390: Waldorf	Somewhat limited Seepage	0.43	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.43
485B: Spillville	Very limited Seepage	1.00	Somewhat limited Piping	0.79	Somewhat limited Deep to water Cutbanks cave	0.81
507: Canisteo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
511: Blue Earth	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
583: Minnetonka	Somewhat limited Seepage	0.57	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.43
585B: Coland	Very limited Seepage	1.00	Very limited Depth to saturated zone Piping Seepage	1.00 0.11 0.06	Somewhat limited Cutbanks cave	0.10
Spillville	Very limited Seepage	1.00	Somewhat limited Piping	0.79	Somewhat limited Deep to water Cutbanks cave	0.81

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
621: Houghton	Very limited Seepage	1.00	Very limited Content of organic matter Depth to saturated zone	1.00	Somewhat limited Cutbanks cave	0.10
638B2: Clarion	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
Storden	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
638C2: Clarion	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
Storden	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
638D2: Clarion	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
Storden	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
638E2: Clarion	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
Storden	Somewhat limited Seepage Slope	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
655: Crippin	Somewhat limited Seepage	0.70	Somewhat limited Piping Depth to saturated zone	0.50	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes, and levees		Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
558: Mayer	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00	Very limited Cutbanks cave	1.00
777: Wapsie	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
777B: Wapsie	 Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
777C: Wapsie	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
787B: Vinje	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.01	Very limited Deep to water	1.00
87C2: Vinje	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.01	Very limited Deep to water	1.00
87D2: Vinje	Somewhat limited Seepage Slope	0.70	Somewhat limited Piping	0.01	Very limited Deep to water	1.00
811: Muskego	Very limited Seepage	1.00	Very limited Content of organic matter Depth to saturated zone Piping	1.00	Somewhat limited Cutbanks cave	0.10
323: Ridgeport	Very limited Seepage	1.00	Somewhat limited Seepage	0.20	Very limited Deep to water	1.00
323B: Ridgeport	Very limited Seepage	1.00	Somewhat limited Seepage	0.20	Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
36B: Kilkenny	Somewhat limited Seepage	0.57	Somewhat limited Hard to pack	0.43	Very limited Deep to water	1.00
36C2: Kilkenny	Somewhat limited Seepage	0.57	Somewhat limited Hard to pack	0.43	Very limited Deep to water	1.00
86D2: Kilkenny	Somewhat limited Seepage Slope	0.57	Somewhat limited Hard to pack	0.43	Very limited Deep to water	1.00
36E2: Kilkenny	Somewhat limited Seepage Slope	0.57	Somewhat limited Hard to pack	0.43	Very limited Deep to water	1.00
36F: Kilkenny	Somewhat limited Seepage Slope	0.57	Somewhat limited Hard to pack	0.43	Very limited Deep to water	1.00
55: Shorewood	Somewhat limited Seepage	0.57	Somewhat limited Hard to pack	0.05	Somewhat limited Deep to water Slow refill Cutbanks cave	0.81 0.43 0.10
133: Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
311: Muskego	Very limited Seepage	1.00	Very limited Content of organic matter Depth to saturated zone Piping	1.00	Somewhat limited Cutbanks cave	0.10
010: Pits	Not rated		Not rated		Not rated	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Winnebago County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes levees	, and	Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
5040: Orthents	Not rated		Not rated		Not rated	
W: Water	Not rated		Not rated		Not rated	